

DESCRIPTION: New PCB (not interchangeable).

We inform you that 2 new pcs were introduced in CGH900 series. Part numbers are not changed (**KB1009** and **KB1011**) but components are different (as in photos below). NOTE : new pcs are not interchangeable with the previous spares because of the different connection.

If you have to replace one of them, please check the spares you find in the machine and compare them to the pcb in photos.

- If the spares in the machine match the Old pcb, you will order: the faulty pcb, the other pcb and the connection cable (**KB1047**).
- If the components in the machine match the New pcb, you will have to order only the faulty component.

